

Using Timer1 in Asynchronous Clock Mode

*Author: Mark Palmer
Microchip Technology Inc.*

INTRODUCTION

This application note discusses the use of the PIC16CXXX Timer1 module as an asynchronous clock. The Timer1 module has its own oscillator circuitry, which allows the timer to keep real-time, even when the device is in SLEEP mode. When the device is in sleep, the oscillator will continue to increment TMR1. An overflow of the TMR1 register causes a TMR1 Overflow Interrupt (if enabled) and will wake the processor from sleep. The interrupt service routine can then perform the desired task.


OVERVIEW

Timer1 is a 16-bit counter with a 2-bit prescaler. Timer1 can be incremented from an internal clock, an external clock, or an external oscillator. Timer1 can be configured to synchronize or not synchronize the external clock sources. Asynchronous operation allows Timer1 to increment when the device is in sleep. Figure 1 is a block diagram of Timer1.

To set up Timer1 for asynchronous operation the Timer1 control register, T1CON, must have the following bits configured:

- TMR1CS set (external clock source)
- T1CKPS1:T1CKPS0 configured for the desired prescaler
- T1SYNC set (asynchronous operation)
- TMR1ON set (enables Timer1)
- T1OSCEN set, if using an external oscillator

FIGURE 1: TIMER1 BLOCK DIAGRAM



In asynchronous operation, if the clock source is an external clock, it is input on the T1CKI pin. If the clock source is a crystal oscillator, the crystal is connected across the T1OSO and T1OSI pins.

When using Timer1 in Asynchronous mode, the use of an external clock minimizes the operating and sleep currents. This is because the timer's internal oscillator circuitry is disabled. Though the external clock may give the lower device currents, the use of a crystal oscillator may lead to lower system current consumption and system cost.

System current consumption can also be reduced by having the TMR1 Overflow Interrupt wake the processor from SLEEP at the desired interval. With a 32.768 kHz crystal, Timer1's overflow rate ranges from 2 to 16 seconds, depending on the prescaler chosen. Table 1 shows Timer1 overflow times for various crystal frequencies and prescaler values.

TABLE 1: TIMER1 OVERFLOW TIMES

Prescale	Frequency (kHz)		
	32.768	100	200
1	2	0.655	0.327
2	4	1.31	0.655
4	8	2.62	1.31
8	16	5.24	2.62

Overflow times in seconds.

AN580

As can be seen the 32 kHz crystal, gives very nice overflow rates. These crystals, referred to as watch crystals, also can be relatively inexpensive. In many applications the 2 second overflow time, of a 32 kHz crystal, is too long. An easy way to reduce the overflow time is to load the TMR1H register with a value, during the interrupt service routine. Table 2 shows the overflow times, depending on the value loaded into the TMR1H register and a prescale of 1.

TABLE 2: TMR1H LOAD VALUES / TIMER1 OVERFLOW TIMES

TMR1H Load Value	Overflow Time (@ 32.768 kHz)
80h	1 Second
C0h	0.5 Second
E0h	0.25 Second
F0h	0.125 Second

Note: The loading of either TMR1H or TMR1L causes the prescaler to be cleared. When Timer1 is in operation, extreme care should be taken in modifying either the TMR1H or TMR1L registers, since this automatically configures the prescaler to 1.

The code segment shown in Example 1 configures the Timer1 module for asynchronous operation, enables the Timer1 interrupt, and the interrupt service routine loads the TMR1H register with a value.

CONCLUSION

Timer1 gives designers a powerful time-base function. The asynchronous operation and internal oscillator circuitry gives designers the ability to easily keep real-time, while minimizing power consumption and external logic.

EXAMPLE 1: TIMER1 CODE SEGMENT FOR ASYNCHRONOUS OPERATION

```

    org    0x000
Reset_V   GOTO    START
;
    org    0x004
PER_INT_V
    BCF    STATUS, RP0    ; Bank0
    BTFSC  PIR1, TMR1IF   ; Timer1 overflowed?
    GOTO   T1_OVRFL      ; YES, Service the Timer1 Overflow Interrupt
;
; Should NEVER get here
;
ERROR1    ; NO, Unknown Interrupt Source
    BSF    PORTD, 1      ; Toggle a port pin to indicate error
    BCF    PORTD, 1
    GOTO   ERROR1
;
T1_OVRFL
    BCF    PIR1, TMR1IF   ; Clear Timer1 Interrupt Flag
    MOVLW  0x80          ; Since doing key inputs, clear TMR1
    MOVWF  TMR1H         ; for 1 sec overflow.
    :
    :                   ; Do Interrupt stuff here
    :
    RETFIE                ; Return / Enable Global Interrupts
;
;
START     ; POWER_ON Reset (Beginning of program)
    CLRF   STATUS        ; Do initialization (Bank0)
    BCF    T1CON, TMR1ON ; Timer1 is NOT incrementing
    :
    :                   ; Do Initialization stuff here
    :
    MOVLW  0x80          ; TIM1H:TMR1L = 0x8000 gives 1 second
    MOVWF  TMR1H         ; overflow, at 32 KHz.
    CLRF   TMR1L        ;
;
    CLRF   INTCON
    CLRF   PIR1
    BSF    STATUS, RP0   ; Bank1
    CLRF   PIE1         ; Disable all peripheral interrupts
;
    if ( C74_REV_A )    ; See PIC16C74 Errata
        BSF    TRISC, T1OSO ; RC0 needs to be input for the oscillator to function
    endif
    BSF    PIE1, TMR1IE ; Enable TMR1 Interrupt
;
; Initialize the Special Function Registers (SFR) interrupts
;
    BCF    STATUS, RP0   ; Bank0
    CLRF   PIR1         ;
    BSF    INTCON, PEIE ; Enable Peripheral Interrupts
    BSF    INTCON, GIE  ; Enable all Interrupts
;
    MOVLW  0x0E
    MOVWF  T1CON        ; Enable T1 Oscillator, Ext Clock, Async, prescaler = 1
    BSF    T1CON, TMR1ON ; Turn Timer1 ON
;
zzz      SLEEP
        GOTO   zzz      ; Sleep, wait for TMR1 interrupt

```



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office

Microchip Technology Inc.
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-786-7200 Fax: 480-786-7277
Technical Support: 480-786-7627
Web Address: <http://www.microchip.com>

Atlanta

Microchip Technology Inc.
500 Sugar Mill Road, Suite 200B
Atlanta, GA 30350
Tel: 770-640-0034 Fax: 770-640-0307

Boston

Microchip Technology Inc.
5 Mount Royal Avenue
Marlborough, MA 01752
Tel: 508-480-9990 Fax: 508-480-8575

Chicago

Microchip Technology Inc.
333 Pierce Road, Suite 180
Itasca, IL 60143
Tel: 630-285-0071 Fax: 630-285-0075

Dallas

Microchip Technology Inc.
4570 Westgrove Drive, Suite 160
Addison, TX 75248
Tel: 972-818-7423 Fax: 972-818-2924

Dayton

Microchip Technology Inc.
Two Prestige Place, Suite 150
Miamisburg, OH 45342
Tel: 937-291-1654 Fax: 937-291-9175

Detroit

Microchip Technology Inc.
Tri-Atria Office Building
32255 Northwestern Highway, Suite 190
Farmington Hills, MI 48334
Tel: 248-538-2250 Fax: 248-538-2260

Los Angeles

Microchip Technology Inc.
18201 Von Karman, Suite 1090
Irvine, CA 92612
Tel: 949-263-1888 Fax: 949-263-1338

New York

Microchip Technology Inc.
150 Motor Parkway, Suite 202
Hauppauge, NY 11788
Tel: 631-273-5305 Fax: 631-273-5335

San Jose

Microchip Technology Inc.
2107 North First Street, Suite 590
San Jose, CA 95131
Tel: 408-436-7950 Fax: 408-436-7955

AMERICAS (continued)

Toronto

Microchip Technology Inc.
5925 Airport Road, Suite 200
Mississauga, Ontario L4V 1W1, Canada
Tel: 905-405-6279 Fax: 905-405-6253

ASIA/PACIFIC

Hong Kong

Microchip Asia Pacific
Unit 2101, Tower 2
Metroplaza
223 Hing Fong Road
Kwai Fong, N.T., Hong Kong
Tel: 852-2-401-1200 Fax: 852-2-401-3431

Beijing

Microchip Technology, Beijing
Unit 915, 6 Chaoyangmen Bei Dajie
Dong Erhuan Road, Dongcheng District
New China Hong Kong Manhattan Building
Beijing 100027 PRC
Tel: 86-10-85282100 Fax: 86-10-85282104

India

Microchip Technology Inc.
India Liaison Office
No. 6, Legacy, Convent Road
Bangalore 560 025, India
Tel: 91-80-229-0061 Fax: 91-80-229-0062

Japan

Microchip Technology Intl. Inc.
Benex S-1 6F
3-18-20, Shinyokohama
Kohoku-Ku, Yokohama-shi
Kanagawa 222-0033 Japan
Tel: 81-45-471-6166 Fax: 81-45-471-6122

Korea

Microchip Technology Korea
168-1, Youngbo Bldg. 3 Floor
Samsung-Dong, Kangnam-Ku
Seoul, Korea
Tel: 82-2-554-7200 Fax: 82-2-558-5934

Shanghai

Microchip Technology
RM 406 Shanghai Golden Bridge Bldg.
2077 Yan'an Road West, Hong Qiao District
Shanghai, PRC 200335
Tel: 86-21-6275-5700 Fax: 86 21-6275-5060

ASIA/PACIFIC (continued)

Singapore

Microchip Technology Singapore Pte Ltd.
200 Middle Road
#07-02 Prime Centre
Singapore 188980
Tel: 65-334-8870 Fax: 65-334-8850

Taiwan, R.O.C

Microchip Technology Taiwan
10F-1C 207
Tung Hua North Road
Taipei, Taiwan, ROC
Tel: 886-2-2717-7175 Fax: 886-2-2545-0139

EUROPE

United Kingdom

Arizona Microchip Technology Ltd.
505 Eskdale Road
Wokingham
Berkshire, England RG41 5TU
Tel: 44 118 921 5858 Fax: 44-118 921-5835

Denmark

Microchip Technology Denmark ApS
Regus Business Centre
Lautrup hof 1-3
Ballerup DK-2750 Denmark
Tel: 45 4420 9895 Fax: 45 4420 9910

France

Arizona Microchip Technology SARL
Parc d'Activite du Moulin de Massy
43 Rue du Saule Trapu
Batiment A - 1er Etage
91300 Massy, France
Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79


Germany

Arizona Microchip Technology GmbH
Gustav-Heinemann-Ring 125
D-81739 München, Germany
Tel: 49-89-627-144 0 Fax: 49-89-627-144-44

Italy

Arizona Microchip Technology SRL
Centro Direzionale Colleoni
Palazzo Taurus 1 V. Le Colleoni 1
20041 Agrate Brianza
Milan, Italy
Tel: 39-039-65791-1 Fax: 39-039-6899883

11/15/99



Microchip received QS-9000 quality system certification for its worldwide headquarters, design and water fabrication facilities in Chandler and Tempe, Arizona in July 1999. The Company's quality system processes and procedures are QS-9000 compliant for its PICmicro® 8-bit MCUs, KEELOC® code hopping devices, Serial EEPROMs and microperipheral products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001 certified.

All rights reserved. © 1999 Microchip Technology Incorporated. Printed in the USA. 11/99 Printed on recycled paper.

Information contained in this publication regarding device applications and the like is intended for suggestion only and may be superseded by updates. No representation or warranty is given and no liability is assumed by Microchip Technology Incorporated with respect to the accuracy or use of such information, or infringement of patents or other intellectual property rights arising from such use or otherwise. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any intellectual property rights. The Microchip logo and name are registered trademarks of Microchip Technology Inc. in the U.S.A. and other countries. All rights reserved. All other trademarks mentioned herein are the property of their respective companies.