



101457B
December 15, 2000

Fusion 878A

errata sheet

Literature Affected: **Fusion 878A Data Sheet 100600B**

Product Affected: **Fusion 878A**

Several errors have been discovered in the current Fusion 878A Data Sheet.

On page ii, "Related Documents" section contains a reference to the Fusion Technical Reference Manual. This is an error as Conexant has no plans to publish this document and the reader should therefore disregard it.

On Page 5-22, the address of the Audio Reset Register (ARESET) is specified incorrectly as 0x5B. The correct address is 0x58.

If you have any questions about this errata, please contact your local Conexant sales office.